## 17-019 QA PRODUCT RECALL – WALTHER CCP PISTOLS DUE TO UNSAFE DROP FIRE HAZARD

Date: 19 April 2017 QA Product Recall: # 17-019

Scope: CONUS Firearm stores

Walther Arms has identified a unsafe condition in its CCP pistols that could potentially cause it to discharge if dropped whether the manual safety is engaged (on) or disengaged (off).

Please do not load or fire your Walther CCP pistol and contact the vendor immediately to arrange to have your pistol upgraded free of charge.

Product Information:

UPC ITEM DESC

723364210419 WAL CCP 9MM 354 STS 8RD

723364205330 WAL 5080300 CCP 9MM BLK 8RD

The upgrade will be done at no charge to you. For free shipping, please enter your information <a href="http://www.waltherarms.com/ccp-information-submission/">here <a href="http://www.waltherarms.com/ccp-information-submission/">http://www.waltherarms.com/ccp-information-submission/</a>, and complete the online form, making sure to include the serial number. After completion of the form a confirmation email will be sent including shipping information. The serial number is located on the right side of the pistol.

Please submit your information here - http://www.waltherarms.com/ccp-information-submission/.

Please check this website and all safety notices on a regular basis for current information about your firearms. You may also contact us by by email at <a href="mailto:ccprecall@WaltherArms.com">ccprecall@WaltherArms.com</a>, by mail at Walther Arms, Inc., 7700 Chad Colley Boulevard, Fort Smith, AR 72916, or by phone at 1-866-503-3389.

The current time to repair your CCP is approximately 4-6 weeks from the time we receive it.