


## Sig Sauer Recalls E9MMB1-50 Ammo Due To Bullet-in-Bore Obstruction

**Recall Date:** 22 August 2022

**Description:** SIG SAUER has determined that portions of Lot No. JDAR0815 of SIG SAUER 9MM, 115gr, Elite Ball, FMJ (SKU E9MMB1-50), may have powder charge variations that could result in a bullet remaining in the barrel (i.e., a bullet-in-bore obstruction). For more information concerning this recall please visit the [Sig Sauer website](#).

The following products and lots were sold at The Exchange:

Product Description	UPC	Lot Code*	Image
SIG SAUER 9MM, 115gr, Elite Ball, FMJ (SKU E9MMB1-50)	798681516889	JDAR0815	

\*The lot number can be found on the inside flap of the individual boxes of ammunition.

**Hazard:** Firing a subsequent bullet into a bore obstruction could cause firearm damage, rendering the firearm inoperable and subjecting the shooter and bystanders to a risk of serious personal injury.

**Remedy:** Customers that have this recalled product should stop using and follow the instructions for customer contact below.

**Incidents/Injuries:** To date, no injuries related to this product have been reported.

**Sold at:** US Exchanges and other retailers.

**Customer Contact:** If you possess ammunition from this lot number or have questions concerning this warning, please register for the recall process at [sigsauer.com/ammorecall-submission](https://sigsauer.com/ammorecall-submission) and instructions for returning your product will be provided or call SIG SAUER Customer Service at 603-610-3000 (Option 1).

**Manufacturer:** Sig Sauer

**Recall #:** 22-023