


# Traeger Pellet Grills Recalls Flat Top Propane Grills Due to Fire Hazard

**Recall Date:** 14 December 2023

**Description:** Traeger Pellet Grills recalls select Flat Top Propane Grills due to incorrectly labeled burner control knobs which can result in the grill being unintentionally left on, posing a fire hazard. For more information, please visit the [manufacturer website](#) or [CPSC website](#).

The following item was sold at The Exchange:

Product	UPC	SKU*	Date Codes*	Sample Image
Traeger Flatrock Flat Top Grill	634868940958	1DFL42LLA	2211 2304 2212 2305 2301 2307 2302 2308 2303 2309	

\*The SKU and Date Code are on the silver data plate on the back of grill. The date code is a 4-digit code (YYMM) located within the Flatrock’s serial number (see the example below). Grills with a red sticker on the data plate have already been inspected and repaired and are not subject to this recall.



If your Flatrock matches the SKU and Date Codes above and does not have a red sticker, follow the instructions in the remedy section below.

**Hazard:** The incorrect burner control knobs can result in the grill fuel supply being unintentionally left in an open position, posing a fire hazard.

**Remedy:** Immediately stop using your Flatrock grill and [click here](#) to follow the manufacturer’s instructions to inspect the burner control knobs and request a free repair kit.

**Incidents/Injuries:** The firm has received 57 reports of flame adjustment knobs being incorrectly labeled. No fires or injuries have been reported.

**Sold at:** The Exchange and other retailers.

**Consumer Contact:** Consumers may contact Traeger toll-free at 833-654-2407 seven days a week from 6 a.m. to 10 p.m. MT or online at [www.traeger.com/recall](http://www.traeger.com/recall) or [www.traeger.com](http://www.traeger.com) and click on “Recall” for more information.

**Manufacturer:** Traeger Pallet Grills

**Recall #:** 23-034