

Ruger SR22 Pistol Due to Slack Trigger Malfunction

Recall Date: 07 April 2022

Description:

Product Description	Serial #	UPC
RUGER SR22PS 22LR SILVER	369-40078 OR LOWER	736676036073
RUGER SR22 22LR 3.5IN BLK		736676036004
RUG SR22PBT 22LR 3.5 BL		736676036042

Hazard

) In rare instances, if the left and right frame inserts of Ruger SR22 pistols are not properly secured together, the firing pin blocker lifter and hammer block can move independently of each other, potentially rendering them ineffective. If this situation occurs, the pistol will intermittently exhibit a “slack” single-action trigger and has the potential to discharge if decocked over a live round.

Remedy:

) Sign up for the firearm retrofit at the contact number shown below.

Incidents/Injuries:

) None reported.

Consumer Contact:

) Ruger.com/SR22Retrofit. Contact Customer Service at 336-949-5200

Manufacturer:

) Ruger & Company Inc.

Manufactured In:

) United States

Recall #: 22-007