Vornado Air Recalls Steamfast Home and Away Steam Irons Due to Fire, Burn, and Shock

Recall Expansion Date: 14 Dec 2023 Recall Date: 27 Apr 2023

Description: Vornado Air is voluntarily recalling select models of Steamfast Home and Away Travel Steam Irons due to a safety concern. For a complete product list and more information, please visit the <u>CPSC</u> <u>website</u>.

The following item was sold at The Exchange:

ITEM DESCRIPTION	UPC	MODEL NUMBER	IMAGE
Steamfast Home and Away Travel Steam Iron	047171717009	SF-717	Streamfast. Tradic stream Rom. Tradic stream

Hazard: The power cord can become damaged near the cord bushing, which can lead to overheating of the cord, posing fire and burn hazards. In addition, cord damage near the bushing can result in exposed copper wires, posing a shock hazard.

Remedy: Consumers should immediately stop using the recalled irons and visit the Steamfast or Vornado website to register for the recall and receive a refund or a free replacement iron.

Incidents/Injuries: Vornado has received a total of 74 reports of incidents, including 18 additional reports of the iron's power cord smoking, sparking, catching fire, or overheating at the power cord, or of the power cord becoming damaged. Vornado has received two reports of minor shocks.

Sold at: Exchange Ecommerce and other retailers.

Consumer Contact: For questions or concerns, consumers can contact Vornado toll-free at 866-827-3362 from 8 a.m. to 5 p.m. ET Monday through Friday or online at <u>www.steamfast.com/recalls/travelirons</u> to start a recall submission. Consumers can also visit <u>www.vornado.com</u> or <u>www.steamfast.com</u>, and click on "Product Recalls" at the top of the page for more information.

Manufacturer: Vornado Air LLC

Recall #: 23-011