

17-025 QA PRODUCT RECALL – DANIELS DEFENSE FIREARMS DUE TO DOUBLE FIRE HAZARD

Date: 1 June 2017

Recall: # 17-025

Scope: Select Exchange Retail Stores

The vendor has communicated to HQ that select models of Daniel Defense firearms manufactured between April 1, 2016 and March 3, 2017 may have a trigger defect.

Hazard: The firearms can discharge twice when the trigger is pulled one time, thereby posing an extreme safety hazard.

Description: The Exchange sold the affected models listed in the table below.

UPC	MODEL
815604015615	V5 556NATO 16IN BLK 10RDM
815604015349	V9 556 16IN BLK 30RD
815604016179	V9 556NATO 16IN GREY 10RD
815604018456	M4V7 556NATO 16IN 32RD

Remedy: Consumers should immediately stop using the recalled firearm and contact Daniel Defense to arrange for a diagnostic test. Daniel Defense will correct any and all potential conditions at no cost to the consumer as part of our 100% Satisfaction Guarantee.

Consumer Contact: If you are unable or unwilling to contact the diagnostic test process, please contact Daniel Defense toll free at: (866)554-GUNS (4867).