

## MOSSBERG SA-410 SHOTGUNS DUE TO MISFIRE HAZARD

**Date:** 25 May 2022

**Description:** this recall notice only applies to the serial numbers of the **SA-410 Shotguns** listed at [Mossberg.com/sa410-recall](https://Mossberg.com/sa410-recall).

UPC	DESCRIPTION
884110757968	SA-410 FIELD 410/26 4R Shotgun
884110757951	SA-410 TURKEY 410/26 B Shotgun

**Hazard:** The firearms hammer can fail to fully engage the sear, causing the round to fire, cycling the slide, and potentially resulting in multiple discharges without depressing the trigger.

**Remedy:** If your SA-410 shotgun is among those listed, please do not load, fire or use your SA-410 shotgun and contact Mossberg immediately to arrange to have your shotgun upgraded free of charge.

**Consumer Contact:** Mossberg requests that you please contact them by email at [SA410Recall@Mossberg.com](mailto:SA410Recall@Mossberg.com), or by calling (203) 230-5300 (Monday through Friday, from 8:00 a.m. to 4:30 p.m. EST).

Recall: # 22-012