

# Yeti Recalls Select Yeti Coolers Due to Magnet Ingestion Hazard

**Recall Date:** 09 March 2023

**Description:** Yeti is voluntarily recalling select Yeti Coolers. The magnet-lined closures can fail and result in detached magnets, posing a risk of serious injury or death if ingested. The affected products were the Hopper M30 soft cooler, Hopper M20 soft backpack cooler and SideKick dry gear case. For a complete product list and more information, please visit the [CPSC website](https://www.yeti.com).

The following items were sold at The Exchange:

Hopper M30 Soft Cooler 1.0				
888830059807  Charcoal	888830059814  River Green	888830059821  Navy	888830068533  Coral	888830098936  Aquifer Blue
888830081693  Sagebrush Green	888830113431  King Crab Orange	888830210789  Nordic Blue	888830210468  Nordic Purple	

Hopper M30 Soft Cooler 2.0			
888830133699  Navy	888830133705  Charcoal	888830190388  Bimini Pink	888830190371  Alpine Yellow

Hopper M20 Soft Backpack Cooler				
888830062753  Charcoal	888830062760  Navy	888830190265  Bimini Pink	888830210796  Nordic Blue	888830210475  Nordic Purple

Hopper Sidekick Dry Gear Case					
888830025567  Fog Gray	888830025574  Field Tan	888830058916  Charcoal	888830067376  Navy	888830068540  Coral	888830085776  Sagebrush Green
888830134047  Harvest Red	888830210710  Nordic Purple	888830190449  Alpine Yellow	888830190456  Bimini Pink	888830210826  Nordic Blue	888830176160  Highlands Olive

**Hazard:** When two or more high-powered magnets are ingested, the magnets can attract to each other, or to another metal object, and become lodged in the digestive system. This can result in perforations, twisting and/or blockage of the intestines, infection, blood poisoning and death.

**Remedy:** Consumers should immediately stop using the recalled products and contact YETI at [www.yeti.com](https://www.yeti.com) to receive a full refund or replacement product.

**Incidents/Injuries:** The firm has received 1,399 reports of the magnet-lined closures degrading or failing, including reports of missing or detached magnets. No magnet ingestions or injuries have been reported.

**Sold at:** Worldwide Exchanges and other retailers.

**Consumer Contact:** Contact YETI toll-free at 833-444-3151 from 7 a.m. to 7 p.m. CT Monday through Sunday, email at [productrecall@yeti.com](mailto:productrecall@yeti.com) or online at <https://www.yeti.com/M20-M30-sidekick-product-recall.html> or at [www.yeti.com](https://www.yeti.com) and click on "Product Recall" at the bottom of the page for more information.

**Manufacturer:** YETI Coolers LLC

**Recall #:** 23-002